

This Service Bulletin replaces Vendor Literature, "Kysor Installation and Service Guide - Fan Hub Series 1077" and "Kysor Service Guide - Rear Air Fan Drive Series 1093", Group 26, PV776-KY39066-01 and PV776-KY43057-01. Also, this Service Bulletin replaces Service Bulletin, "Fan Clutch Literature", Group 26, PV776-TSP161572.

Date	Group	No.	Page
4.2003	263	039	1(1)

Fan Literature
VN, VHD

Fan Literature

Kysor

Copies of service literature for Kysor components can now be accessed directly from the official internet site of the Quik-Cool Corporation.

To review and download Kysor service literature, please visit:

<http://www.quikkool.com/serviceinfo.html>

Bendix

Copies of service literature for Bendix components can now be accessed directly from the official internet site of the Bendix Corporation.

To review and download Bendix service literature, please visit:

<http://www.bendix.com/products/FanClutches.shtml>