
Date	Group	No.	Page
5.2003	381	33	1(1)

Instrument Cluster Repair
Warranty Coverage
VN, VHD

Instrument Cluster Repair

This service bulletin details the warranty repair and replacement recommendations for the Dixon and Pollak Instrument clusters. For further information concerning instrument clusters refer to Group 3.

Dixon

Starting immediately all Dixon 96 and 96B clusters should be repaired rather than completely replaced as long as the repair does not exceed 75% of the cost of a cluster replacement, during the warranty period of the cluster.

Pollak

Starting immediately all 98 Pollak clusters should be repaired rather than replaced as long as the cluster has been in service for over 1.5 years and/or has over 150,000 miles, during the warranty period of the cluster.