

Date	Group	No.	Page
10.2002	643	001	1(1)

TRW Ball Socket Wear
Procedure Literature
VN, VHD

Ball Socket Wear

Procedure Literature

(Effective from October 2002)

Service Bulletin, "Inspection Procedure for TRW Ball Socket Wear", LNK-105 (03.2002) can now be accessed directly from the official internet site of TRW Corporation.

To review and download this TRW Service Bulletin, please visit:

<http://trucksteering.trw.com/files/Lnk105.pdf>

NOTE: This document is subject to change without notice.