

This Service Bulletin replaces Vendor Literature, "Hendrickson HLU5 Maintenance Guide", "Hendrickson HLU5 Installation Instructions", and "Hendrickson HLM1 Installation Instructions", Group 6, PV776-H-622, PV776-HEN-H633A, and PV776-L-56A.

Date	Group	No.	Page
3.2003	610	002	1(1)

Suspension Literature
VN, VHD

Suspension Literature

Hendrickson

Copies of service literature for Hendrickson components can now be accessed directly from the official internet site of the Hendrickson International Corporation.

To review and download Hendrickson service literature, please visit:

<http://www.hendrickson-intl.com/literature/>