

Service Bulletin Trucks

 Date
 Group
 No.
 Page

 8.2002
 922 005 1(1)

Fifth Wheel Ramp VN, VHD

Fifth Wheel Ramp

As a result of field reports and customer issues with the shorter style 5th Wheel Ramp, a longer style ramp has been made available for both production and service use for the VN/VHD vehicles. The longer ramps were implemented May 2002.

Frame Style	Part No. Replaced**	New Part No.
RH High Frame	20435600	8078092
LH High Frame	20435599	8078091
RH Low Frame	20353621	8078021
LH Low Frame	20353620	8078020

The ramps are available for use on an as needed basis. Ramps are usually Huck bolted to the framerail and must be cut to remove. Use proper grade 8 bolt and nut fasteners during replacement. The suggested fastener part no. is 8397030 (locking nut). Torque the bolt to 283.78 ± 13.5 Nm (105 ft-lb).

**The part numbers replaced on 6x4 and 8x4, will continue to be used on 4x2 tractors.

For further information concerning the Fifth Wheel refer to Service Manual 922-501, Fifth Wheel, All Models, Publication Number PV776-TSP148827, Publication date 03.2001.