



Volvo Trucks North America, Inc.
Greensboro, NC USA

Contents: Group 87-99

VN, VHD VERSION2

| Publication # | Edition Title | Date | Publication Order # |
|-----------------|--|-------|---------------------|
| Group 3 | Electrical | | |
| | Service Bulletin | | |
| 891-03 | Lock Cover Assembly, Installation | 09/04 | PV776-20013583 |
| Group 87 | Climate Unit | | |
| | Service Bulletin | | |
| 870-15 | Climate Unit Stepper Motor Testing | 12/03 | PV776-20001146 |
| 873-10 | Climate Control, Sleeper | 01/04 | PV776-TSP177729 |
| 873-16 | Webasto Parking Heater | 07/04 | PV776-TSP197085 |
| 874-21 | Cab Climate Unit, Specifications, Design and Function | 04/04 | PV776-20007445 |
| 874-22 | Climate System Troubleshooting | 11/03 | PV776-TSP197430 |
| 874-23 | Cab Climate System, Repair Instructions | 11/02 | PV776-TSP177236 |
| | Service Manual | | |
| 87 | Fault Codes, Climate Control MID 146 | 10/03 | PV776-TSP196483 |
| Group 88 | Interior Equipment | | |
| | Service Bulletin | | |
| 880-02 | Safety Belts Inspection | 11/02 | PV776-TSP180931 |
| 884-06 | SRS Repair | 11/02 | PV776-TSP177240 |
| 884-07 | SRS, Safety Belts and Bunk Restraints, Design and Specifications | 11/02 | PV776-TSP182323 |
| 885-01 | Sink - VNL VERSION2 | 11/02 | PV776-TSP180932 |
| 885-02 | Refrigerator Literature | 05/03 | PV776-TSP187909 |
| | Service Manual | | |
| 88 | SRS Fault Code and Troubleshooting Manual | 01/03 | PV776-TSP180934 |
| Group 89 | Miscellaneous | | |
| | Service Bulletin | | |
| 891-02 | Air Fairing Repair - VN VERSION2 | 11/02 | PV776-TSP180933 |
| 897-01 | License Plate Mounting | 05/03 | PV776-TSP189710 |

I = New item since last release

| Publication # | Edition Title | Date | Publication Order # |
|----------------------|--|-------------|----------------------------|
| Group 90 | General | | |
| | Service Bulletin | | |
| 900-154 | Bodybuilder Module (BBM) Installation Kit | 02/03 | PV776-TSP186005 |
| 900-27 | General Safety Practices, Miscellaneous | 11/02 | PV776-TSP181765 |
| Group 92 | Mechanical Equipment | | |
| | Service Bulletin | | |
| 922-05 | Fifth Wheel, Troubleshooting | 11/02 | PV776-TSP180801 |
| 922-09 | Fifth Wheel, Service Procedures | 04/03 | PV776-TSP188402 |
| 922-10 | Fifth Wheel, Design and Function | 03/03 | PV776-TSP188380 |
| 922-11 | Fifth Wheel, Specifications | 03/03 | PV776-TSP188399 |
| 922-12 | Fifth Wheel Air Release | 08/04 | PV776-20 015616 |
| 922-15 | Fifth Wheel Literature | 03/03 | PV776-TSP188201 |
| Group 93 | Electrical Equipment | | |
| | Service Bulletin | | |
| 93 | Bodybuilder Module, Fault Codes MID 249 SID 240 Program Memory | 10/04 | PV776-20017953 |
| | Service Manual | | |
| 93 | MID 249 Bodybuilder Module Fault Codes | 02/03 | PV776-TSP186410 |

I = New item since last release