


This Service Bulletin is a supplement to the Service Manual Instrumentation, VNL, VNM, Group 38, PV776-TSP23762/1.

Date	Group	Supp.	Page
9.98	38	05	1(1)

Instrumentation
VNL, VNM

Volvo Bulb Removal Tool



P/N 1089953

W3000642



CAUTION

Use only the Volvo bulb removal tool, P/N 1089953, to remove bulbs, or damage to the cluster may occur.

In the Tools section of Service Manual *Instrumentation, VNL, VNM, PV776-TSP23762/1*, the bulb removal tool is incorrectly identified.

The part number for the Volvo Bulb Removal tool should read 1089953. This is the only tool recommended for bulb replacement on the 1996 and 1996B Instrument clusters. Please note this correction on page 7 of your *Instrumentation, VNL, VNM Service Manual*.