

This Service Bulletin is a supplement to Service Manual, Anti-Lock Brake System (ABS) Rockwell Wabco (VN/VHD), 593-501, (PV776-TSP139834).

Date	Group	Supp.	Page
10.00	593 501	01	1(1)

Anti-Lock Brake System (ABS) Rockwell Wabco
VN, VHD

Anti-Lock Brake System (ABS) Sequence Number Correction

In the Anti-Lock Brake System (ABS) Rockwell Wabco (VN/VHD) Manual, 593-501, (PV776-TSP139834) the "ABS ATC Valve, Replacement" procedure is assigned an incorrect sequence number, "22". The correct sequence number is "25". The correct procedure number is 5631-03-02-25.