



Volvo Trucks North America, Inc.
Greensboro, NC USA

Contents: Group 40-59

VN, VHD VERSION2

Publication #	Edition Title	Date	Publication Order #
Group 40	General		
	Service Bulletin		
400-20	General Safety Practices, Transmission	11/02	PV776-TSP182219
Group 41	Clutch		
	Service Bulletin		
411-36	Clutch, Adjustment, Eaton Easy Pedal	11/03	PV776-TSP191565
Group 43	Transmission		
	Service Bulletin		
431-192	Transmission Literature, Eaton	11/02	PV776-TSP182389
431-193	Transmission Literature, Allison	11/02	PV776-TSP182390
431-194	Transmission Literature, Meritor	11/02	PV776-TSP182391
Group 45	Driveshafts		
	Service Bulletin		
451-22	Driveshaft Literature, Spicer	11/02	PV776-TSP182392
451-23	Drive Shaft Phase Angles	11/02	PV776-TSP182393
Group 46	Rear Axle, Axle Shafts		
	Service Bulletin		
460-14	Rear Axle Literature, Eaton	11/02	PV776-TSP182394
460-15	Rear Axle Literature, Meritor	11/02	PV776-TSP182395
Group 48	Power Take-Off		
	Service Bulletin		
482-19	Side-mounted Engine PTO, Installation and Troubleshooting	03/03	PV776-TSP188567
	Service Manual		
48	Rear Engine Power Take Off, VHD, D12D	12/04	PV776-20 006578
Group 49	Miscellaneous		
	Service Bulletin		
491-01	Europower Fittings	09/05	PV776-20 036561
491-027	Maintenance List for Transmission Oil Cooler	07/05	PV776-20029012

| = New item since last release

Publication #	Edition Title	Date	Publication Order #
Group 50	General		
	Service Bulletin		
500-58	General Safety Practices, Brakes and Air Systems	11/02	PV776-TSP181768
500-61	Brake Literature	07/03	PV776-TSP194944
Group 52	Hydraulic Brake System		
	Service Bulletin		
524-01	Brake Pedal Adjustment	11/04	PV776-20 018203
Group 56	Compressed Air Brakes		
	Service Bulletin		
560-26	Compressed Air Brakes, Design and Function	11/02	PV776-TSP175458
560-27	Compressed Air Brakes, Specifications	11/02	PV776-TSP175457
560-28	Compressed Air Brakes, Troubleshooting	11/02	PV776-TSP175459
560-31	Compressed Air Brakes, Service Procedures	11/03	PV776-20 000969
562-02	Air Tank Push-in Fittings	05/03	PV776-TSP190485
563-77	Air Solenoids	11/02	PV776-TSP182388
563-79	Foot Brake Valve - E6	07/03	PV776-TSP191235
563-88	Air Solenoids, Herion Solenoid Valve	04/05	PV776-20 020128
	Service Manual		
56	Air Brake System Schematic and Routing - VHD VERSION2	11/02	PV776-TSP178761
56	Air Brake System Schematic and Routing - VN VERSION2	11/02	PV776-TSP178762
Group 59	Miscellaneous		
	Service Bulletin		
593-37	Anti-Lock Brake System (ABS), Meritor WABCO Design and Function	03/04	PV776-20 002329
593-38	Anti-Lock Brake System (ABS), Meritor WABCO Specifications	01/04	PV776-20 002474
593-39	Anti-Lock Brake System (ABS), Meritor WABCO Troubleshooting	01/04	PV776-20 002475
593-40	Anti-Lock Brake System (ABS), Meritor WABCO Service Procedures	03/04	PV776-20 004223
593-41	WABCO ABS Sensor Installation	02/03	PV776-TSP185202
593-57	Anti-Lock Brake System-6, Bendix	08/05	PV776-20 034318

I = New item since last release