

Fleet Name SAMPLE REPORT		Unit #	VIN # (last 6)
Location		Contact	
Address		Phone	
City	State	Zip	
Year <u>2000</u> Make <u>Volvo</u>		Frame <input checked="" type="radio"/> Steel Aluminum Double	
Model <u>VNL64T660</u>		Interior Type (Name) <u>Legacy Vinyl II</u>	
Full VIN # <u>4V4ND4G48YN</u>		Interior Level Low <input checked="" type="radio"/> Mid High	
Engine Make <u>Volvo</u>		Interior Upholstery Vinyl <input checked="" type="radio"/> Cloth <input checked="" type="radio"/> Button-Tuck	
Model <u>VE D12-465</u> HP <u>463</u>		Seat Suspension None LH Air <input checked="" type="radio"/> Dual Air	
Sleeper None Box-Flat Box-Mid Box-Raised		Fuel Tanks Steel <input checked="" type="radio"/> Aluminum	
Integral-Flat Integral-Mid <input checked="" type="radio"/> Integral-Raised		Capacity Tank 1 <u>75</u> Tank 2 <u>125</u> Tank 3	
Sleeper size <u>66"</u>		Bumper <input checked="" type="radio"/> Aero Chrome Steel/Alum	
Wheel Base <u>213"</u>		Interior Color <u>Gray + Black</u>	
Odometer <u>502196</u> ECU <u>502377</u>		Paint Color <u>Red</u>	
Transmission Make <u>Fuller</u>		Exhaust <input checked="" type="radio"/> Single Dual <input checked="" type="radio"/> Vertical Horizontal	
Model <u>RTAO-16710C-AS</u> Speeds <u>10</u>		Front Wheels <input checked="" type="radio"/> Aluminum Steel Spoke	
Type Manual Automatic <input checked="" type="radio"/> Auto-Shift		Radio <input checked="" type="radio"/> AM/FM Cassette <input checked="" type="radio"/> CD Weather Band	
Suspension <input checked="" type="radio"/> Air-Ride Spring Heavy		PTO Yes <input checked="" type="radio"/> No	
Front Axle Make <u>Meritor</u> Capacity <u>12500</u>		Mirrors <input checked="" type="radio"/> Heated RH Power <input checked="" type="radio"/> Dual Power	
Front Axle Position Set-Forward <input checked="" type="radio"/> Set-Back		Wet Line Kit Yes <input checked="" type="radio"/> No	
Rear Axle Make <u>Meritor</u> Capacity <u>40000</u>		Rear Wheels <input checked="" type="radio"/> Aluminum Steel Alum Outside Spoke	
Type Single <input checked="" type="radio"/> Tandem Ratio <u>3.58</u>		Brakes <input checked="" type="radio"/> ABS <input checked="" type="radio"/> Air Hydraulic <input checked="" type="radio"/> Drum Disc	
3rd Axle <input checked="" type="radio"/> None Pusher Tag Lifiable		New Paint Yes <input checked="" type="radio"/> No	
Power Steering <input checked="" type="radio"/> Yes No		Dual Beds Yes <input checked="" type="radio"/> No	
Engine Brake None Jake Driveline <input checked="" type="radio"/> Exhaust		Steer Axle Brakes <u>50% CL 45% BD</u>	
Air Conditioning <input checked="" type="radio"/> Yes No		Drive Axle Brakes <u>70% 70%</u>	
Fuel Type Gas <input checked="" type="radio"/> Diesel		3rd Axle Brakes (if applicable) % %	
Chassis Fairings None Partial <input checked="" type="radio"/> Full		Brake Backing Plates (Dust Shields) Yes <input checked="" type="radio"/> No	
Roof Fairing Yes <input checked="" type="radio"/> No Side Extenders <input checked="" type="radio"/> Yes No		Engine Serial #	
Cab Type Cabover <input checked="" type="radio"/> Conventional		Engine CPL / Arrange. #	
Body Type <input checked="" type="radio"/> Tractor Truck Cab & Chassis		Engine Hours <u>23110</u>	
Exterior Visor None <input checked="" type="radio"/> Fiberglass Aluminum/Stainless		Wheel Mounting Stud-Pilot <input checked="" type="radio"/> Hub-Pilot Spoke	
5th Wheel None Stationary Manual <input checked="" type="radio"/> Air		<p align="center">Brake Legend</p> <p align="center">BD = Bad Drum CL = Cracked or Separated Lining LS = Leaking Seal</p> <p align="center">Tire Legend</p> <p align="center">C = Cut D = Dry Rot F = Flat M = Mismatched Tread or Casings</p> <p align="center">R = Recap V = Virgin W = Irregular Wear X = Capped More Than Once</p> <p align="center">Tread Legend</p> <p align="center">H = Highway L = Lug</p>	
Tire Size Front <u>295/75R 22.5</u>			
Rear <u>295/75R 22.5</u>			
W			
<u>7/32</u>	<u>14/32</u>		
R	R		
<u>17/32</u>	<u>17/32</u>		
RM	RM		
<u>16/32</u>	<u>19/32</u>		
R	R		
<u>3/32</u>	<u>4/32</u>		
RX	RX		
<u>18/32</u>	<u>21/32</u>		
132	132		
<u>132</u>	<u>132</u>		

Inspector **Keith Weatherholt**

Date 11/17/04

CONDITION REPORT

VIN # (last 6)

		ENGINE COMPARTMENT	PIC #	ESTIMATE
✓	Engine oil - Condition & Level			
✓	Coolant - Level & Condition			
✓	Record coolant protection level <u>-45°F</u>			
✓	Radiator, reservoir, hoses			
✓	Fan hub / clutch, blade, shroud			
✓	Air intake - manifold, air-to-air & piping			
✓	Belt alignment, condition & adjustment			
✓	A/C compressor, clutch & brackets			
✓	Engine oil & fuel leaks			
X	Steering gear, draglink, pump & hoses	Draglink End Loose, Axle Side		250
✓	Air compressor, governor & hoses			
✓	Exhaust system - manifold, turbo & piping			
✓	Starter & solenoid			
✓	Charging system - Record voltage <u>13.7</u>			
		INSIDE CAB AND SLEEPER	PIC #	ESTIMATE
X	Start engine - Listen for unusual noises	Eng. Noise	Diagnose	125
✓	Clutch & clutch brake adjustment			
✓	Steering wheel, tilt column, shafts & u-joints			
X	Glass - windshields, doors & mirrors	1 W/S Side Air Deflector Missing - Both	1-21	100
✓	Windshield wipers & washers			
✓	Mirrors - heat & power operation & condition			
✓	Door hinges, latches, regulators & knobs			
X	Seats - air operation & condition	Driver Seat Arm Rest Missing	1-13	75
✓	Seat belts & bunk restraints			
X	Upholstery, carpet, mats, etc....	Upper Storage Comp. Door Missing	1-14	
X	Sleeper / cab privacy curtains & tracks	Rt. W/S Curtain Unhung, Both Tracks loose	1 ¹⁵ / ₁₆	75
X	Cabinets, doors & hinges	L Cabinet Top 2 Drawers Not Latching		50
X	Dash, gauges, switches & interior lights	2 Indicator Lts Out		50
✓	Engine monitor display & LCD readout			
	Engine brake			
X	Radio & speakers	Not Working Properly		250
X	Horns - city & air	1 Electric Horn Button Not Working		25
✓	Parking brake			
✓	Air pressure build up - Governed psi <u>125</u>			
✓	Air leaks - dash, foot valve, shift knob, etc...			
✓	HVAC system, fans, control panels & vents	A/C Not Working		400

**CONDITION REPORT
Supplement Sheet**

VIN # (last 6) _____

PAINT CONDITION & PHYSICAL DAMAGE	PIC #	ESTIMATE
Bumper Scratched + Paint Pitted	2- 8	250
Rt Fender Cracked @ Wheel Well + Below Park Lt	2- 9 / 10	350
L Lower Cab Ext. Rear Edge @ Bottom Cracked	2- 11	150
L Upper Long Fairing Rear Edge Cracked	2- 12	200
L Rear Short Fairing Paint Scratched @ Bottom	2- 13	250
L Rear Short Fairing Brackets Bent	2- 14	150
Rt Side Cat Walk Bent + Mounting loose	2- 15	100
Grill Dented + Cracked Rt. Side	2- 18 / 19	500
MECHANICAL DEFICIENCY (OIL LEAKS, LIGHTS, ETC...)	PIC #	ESTIMATE
Bunk Latch Unmounted	1- 18	25
Both Storage Comp. Lts Out		50
Rt Park Lt Out		25
MISCELLANEOUS (NOTES, ETC...)	PIC #	ESTIMATE
Center Cup Holder in Cab Broken	1- 17	100
CB Strap Missing	1- 17	25
1 Tow Hook Missing		75
Cables Close to Front Drive Line @ Trans		25
Both Plastic Shields on Top of Frame @ Eng. Comp., Broken + Cut	1- 19 / 20	200
Rt Side Panel Above Pass. Seat Missing		75
Both Bunk Window Curtains Missing	1- 25	100
Rear of Cab Paint Rubbed in Middle	2- 16	150
Rear of Cab Bent @ Bottom Corner Above Exhaust	2- 17	350
Total Recon Estimate (supplement sheet only)		\$ 3150

CONDITION REPORT

VIN # (last 6) _____

UNDER VEHICLE		PIC #	ESTIMATE
<input checked="" type="checkbox"/>	Front axle, king pins, tie rod & ends		
<input checked="" type="checkbox"/>	Engine & transmission mounts		
<input checked="" type="checkbox"/>	Frame & crossmembers		
<input checked="" type="checkbox"/>	Air leaks on outside of truck		
<input checked="" type="checkbox"/>	Drain wet tank - oil in air system?		
<input checked="" type="checkbox"/>	Air dryer		
	Hydraulic brake lines & components		
<input checked="" type="checkbox"/>	Brake hoses - cracking & chafing		
X	Brake drums & linings Steer Axle Brakes + Drums		300
<input checked="" type="checkbox"/>	Wheel seals - leaks, etc...		
<input checked="" type="checkbox"/>	Driveshafts, u-joints, yokes, carrier bearing		
<input checked="" type="checkbox"/>	Transmission & rear axle - condition & leaks		
<input checked="" type="checkbox"/>	Rear axle & suspension alignment		
X	Suspension - springs, pins, hangers, etc... Rear Torque Arm Rubber Worn	1-27	200
<input checked="" type="checkbox"/>	Shocks, bushings & mount brackets		
OUTSIDE OF TRUCK		PIC #	ESTIMATE
<input checked="" type="checkbox"/>	Mufflers, stanchion mounts, guards		
<input checked="" type="checkbox"/>	Cab / sleeper air ride & mounting		
X	Mirrors & mounting brackets Both CB Antennas Missing		50
X	Lights & reflectors Rear Tail + Turn Signals Out		100
<input checked="" type="checkbox"/>	Trailer cord, air lines, glad-hands, hangers		
X	Tires & wheels 1 Steer 5 Drive RFI Steel Wheel		1250
<input checked="" type="checkbox"/>	Fuel tanks & mounting		
<input checked="" type="checkbox"/>	Batteries, cables & terminals		
<input checked="" type="checkbox"/>	5th wheel - plate, bushings, cylinder, etc...		
X	Mud flaps, 1/4 fenders, brackets Rt Rear Bracket Bent + Flap Torn	2-7	50
PAINT CONDITION & PHYSICAL DAMAGE		PIC #	ESTIMATE
X	Rt Head Lt Inside Cover Missing	1-23	50
X	Rt Inner Fender on Hood 2 Fasteners Missing	1-24	50
X	L Front Inner Fender Broken	1-22	250
X	Rt Upper Cab Ext. Cracked @ Bottom	1-26	300
X	Rt Lower Cab Ext. Mounted Incorrectly + Cracked @ Rear Lower Edge	2- 3	450
X	Rt Upper Long Fairing Cracked @ Rear Mount	2-4	300
X	Rt Lower Long Fairing Cracked @ Middle + Front of Step	2- 5 / 6	1200
Total Recon Estimate (include supplement sheet total if applicable)			\$ 9100
Supplement Damage Sheet Attached: <input checked="" type="radio"/> Yes <input type="radio"/> No			

Copy Received By: _____