

| Date | Group | No. | Page |
|--------|------------|------------|--------|
| 5.2003 | 175 | 003 | 1(1) |

This Service Bulletin is a supplement to Service Bulletin, "Oil and Filter Change Intervals, Volvo Components, Group 175, PV776-TSP183299.

Oil Analysis Rear Axle and Front Hubs VN, VHD

Oil Analysis

Rear Axle and Front Hubs

When performing an oil analysis of the rear axle, and water content of the oil is requested, use method ASTM D-6304, Procedure C. If the water level is greater than 0.3%, drain and replace the oil.

Note: Other methods of measuring water content during oil analysis may give inaccurate results.